

REVISIONS

REV	DESCRIPTION	DATE	APPROVED
A	VERSION 1.2.0	1/17/17	RH

Full Documentation & Code : "\\fetco-file\Software\Firmware_Releases\1051.00020.00\v3.0.15_Release"

Significant Changes:

1. Error Code Storage is increased from 3 to 8 locations
2. Program space is increased from 512K to 1024K (Bootloader change) to support a new STM32F103 processor which has 1024K flash

BOOT CODE:

1. BLTEMP.BIN - Bootloader (MD5 Checksum: 3395e5a1ef3a2fd59b13e3c1d7308f8c)
2. BOOTLDR.BIN - Bootloader (MD5 Checksum: 167c26db035f43e6b5904456c85f0706)
3. CBS2130.blb - Bootloader (MD5 Checksum: 3d330ebd83e4133c117e5d64580d0dce)
4. CBS2130.BLT - Bootloader (MD5 Checksum: 3395e5a1ef3a2fd59b13e3c1d7308f8c) same as BLTEMP.bin

--	--	--	--

CODE & DOCUMENTATION DIRECTORY:
 \\fetco-file\Software\Firmware_Releases\1051.00020.00



FOOD EQUIPMENT TECHNOLOGIES COMPANY
 600 ROSE ROAD, LAKE ZURICH, IL 60047 USA
 PHONE: (800) 338-2699 FAX (847) 719-3001
 EMAIL: engineering@fetco.com www.fetco.com

NOTES:

BOOTLOADER, CBS-2100 XTS

CREATED BY RICHARD HOPPEL	DRAWN BY RICHARD HOPPEL	SIZE A	DATE 1/17/2017	DWG NO 1050.00019.BL	REV A
FILENAME 1050.00019.BL.VSDX		SCALE 1 : 1	SHEET		1 OF 1